Approved For Release 2001/07/17: CIA-RDP74-00005R000100080023-1

28 July 1971

QUESTIONS AND STATEMENTS BY USING SERVICE AT WEEKLY MEETING

- 1. You all have copies of my observations for 7-26 & 7-27 1971. I intend to do this each day in an effort to improve communications. As various observations are taken care of they will be dropped from the list.
- 2. At the meeting last week I asked "Who is to say whether the rails are straight and plumb (not canted)". I would, now, like to add the words: "and centered".
- 3. What is the status of the metal strips for the grooves by the chain and guide rails -- Have and the contractor reached an agreement as yet?
 - 4. What is the status of the wheels for the record handling equipment?
- said last week (page 7) that: "We have gone through the trial and error period and now would like to freeze the design."
 While I do not agree that the design is ready to be frozen as yet,
 I do agree that we should try to stop the trial and error process.
 I believe that this can be done if the factory engineer will come to the job site and complete the design work that he did not do on the mock-up at the factory or shop drawings. I am particularly concerned about the placement of the equipment on the top shelf (see photo). I realize that our practice of storing on top shelf is different from most other operations, but it means a total of 10% in our overall storage utilization.

25X1A9a

